#### Stáisiún Uí Chonghaile, Baile Átha Cliath 1, D01 V6V6

Connolly Station, Dublin 1, D01 V6V6

T 01 703 4293 E foi@irishrail.ie W www.irishrail.ie



10th November 2021

Email:			

#### IE\_FOI\_520 Response Letter



I refer to your request dated 04<sup>th</sup> October 2021 made under the Freedom of Information Act 2014, which was received by my office on that date, for records held by larnród Éireann.

#### Request:

 Engineering reports, public assessments, and traffic modelling (vehicular, cycling & pedestrian), and Correspondence with Dun Laoghaire Rathdown co council or contractors relating to bridge OBR130 Carbawn Lane, Shankill Co. Dublin, particularly with regard to its condition and proposed upgrade works..

#### Response:

Please find documents attached

#### Rights of appeal

In the event that you are not happy with this decision you can make an appeal in relation to this matter, you can do so by writing to the FOI Unit, Corporate Communications, larnród Éireann Irish Rail, Connolly Station, Amiens St, Dublin 1 or by e-mail to foi@irishrail.ie. You should make your appeal within 4 weeks (20 working days) from the date of this notification, where a day is defined as a working day excluding, the weekend and public holidays, however, the making of a late appeal may be permitted in appropriate circumstances.

The appeal will involve a complete reconsideration of the matter by a more senior member of the staff of this body.

Should you have any questions or concerns regarding the above, please contact the FOI Officer by email at  $\underline{\text{foi@irishrail.ie}}$ 

Yours Sincerely,

P.P



**Decision maker** 

### Freedom of Information Request:

Schedule of Records for IE\_FOI\_520 : Summary for Decision Making

Record No.	Date of Record	Brief Description	No. of Pages	Decision: Grant/Part Grant/Refuse	Section of Act if applicable	Record Edited/Identify Deletions
1	24-Sep-19	2019 PI OBR130	14	Grant		
2	~	Scoring Definitions	1	Grant		
3	~	RE_ Irish Rail PO - 4501108449 - CANCELLED	6	Part Grant	\$37	Personal data of others

# **Bridge - Principal Inspection**

Work Order Number 530462217	Work Order Description Principal Inspection
Equipment Reference OBR130	Equipment Description 130 Corbawn Lane / Public Rd
User (Work Group) MAGUIRE_J (DUB-STSE)	Completion Date 24/09/2019
Summary Description Principal Inspection	·

# REVIEW NOTIFICATIONS

Script Question	Response	Free Text
Have you reviewed existing Notifications? If not, please save and exit script and navigate to Notifications		

# HEADER DATA

Script Question	Response	Free Text
Serial number.	OBR130	
Start mileage Start yardage End mileage End yardage.	011.0509 - 011.0509	
Location accuracy.	2	
 Capture GPS at the centre of the bridge.	53.23551630 -6.11676031	
 HIDDEN - NORTHING	NORTHING	
 HIDDEN - EASTING	EASTING	
Object type.	IPBO	

# HEADER DATA

Script Question	Response	Free Text
 Bridge / Span Function.		

# HEADER DATA

Script Question	Response	Free Text
 Number of spans.		
 Span length (metres).		
 Skew / square.		
 UB clearance (metres).		
 <<<		

# HEADER DATA

Script Question	Response	Free Text
 Number of spans.		
 Span length (metres).		
 Skew / square.		
 Scour Vulnerability Rating.		
 <<<		
 <<<		

# HEADER DATA

Script Question	Response	Free Text
 Bridge / Span Function.	PUBLIC ROAD	
 Number of spans.	1	

 Span length (metres).	8.484	
 Skew / square.	SQUARE SPAN	
 <<<		

# SPECIAL REQUIREMENTS

Script Question	Response	Free Text
Do you wish to capture any special requirements?	NO	
 Please specify the special requirements.		

# STRUCTURAL INSPECTION - SPAN

Script Question	Response	Free Text
Span construction type.	TROUGHING	
 Span material 1.	STEEL	
 Span material 2.	N/A	
 Span condition (Current condition score: =\$ASSET_7A-SC).	3	
 HIDDEN - SPAN CONDITION MEASUREMENT POINT IDENTIFIER.	226959	

# STRUCTURAL INSPECTION - ABUTMENT

	Script Question	Response	Free Text
	Abutment material.	STONE	
:	Abutment construction type.	RETAINING	
:	Abutment condition (Current condition score: =\$ASSET_7B-AC).	2	

### STRUCTURAL INSPECTION - PARAPETS

Script Question	Response	Free Text
Parapet material.	STEEL	
 Parapet construction type.	HANDRAIL	
 Parapet condition (Current condition score: =\$ASSET_7C-PC).	3	
 HIDDEN - PARAPET CONDITION MEASUREMENT POINT IDENTIFIER.	226961	

# STRUCTURAL INSPECTION - SPANDREL WALL

Script Question	Response	Free Text
Spandrel wall material.		
 Spandrel wall condition (Current condition score: =\$ASSET_7D-SDC ).		
 HIDDEN - SPANDREL WALL CONDITION MEASUREMENT POINT IDENTIFIER.		

### STRUCTURAL INSPECTION - WING WALL

Script Question	Response	Free Text
Wing wall material.	STONE	
 Wing wall condition (Current condition score: =\$ASSET_7E-WC).	3	
 HIDDEN - WING WALL CONDITION MEASUREMENT POINT IDENTIFIER.	226962	

### STRUCTURAL INSPECTION - BEARING / BEDSTONES

Script Question	Response	Free Text
Bearing / bedstones material.	STONE	
 Bearing / bedstones construction type.	BEDSTONE	
 Bearing / bedstones condition (Current condition score: =\$ASSET_7F-BBC).	2	
 HIDDEN - BEARING / BEDSTONES CONDITION MEASUREMENT POINT IDENTIFIER.	226963	

# STRUCTURAL INSPECTION - BALLAST RETENTION

Script Question	Response	Free Text
Ballast retention material.		
 Ballast retention condition (Current condition score: =\$ASSET_7G-BRC).		
 HIDDEN - BALLAST RETENTION CONDITION MEASUREMENT POINT IDENTIFIER.		

# MISC QUESTIONS

Script Question	Response	Free Text
Is a notification required for signage (track level and road level as required)?	NO	
 Please use Scripts icon to raise Notifications.		
Is a notification required for scour / blockages in the channel?		
 Please use Scripts icon to create Notification.		

Is a notification required for bridge drainage issue (weep holes, water proofing etc.)?	NO	
 Please use Scripts icon to create Notifications.		

# UPDATE NOTIFICATIONS

Script Question	Response	Free Text
Do you need to update any of the existing Notifications?	NO	
 Please save and exit script. Navigate to Notifications and update as required.		

### CREATE NOTIFICATIONS

Script Question	Response	Free Text
Do you need to create any additional Notifications?	NO	
 Please use Scripts icon to raise further Notifications.		

# GENERAL COMMENTS

Script Question	Response	Free Text
Do you wish to capture additional comments?	YES	

### GENERAL COMMENTS

Script Question	Response	Free Text

 Additional comments.	Longitudinal steel troughing in poor condition, corrosion evident throughout with corrosion at bearings in worst condition. Notifications exist for surface preparation and painting. Steel parapets offer little lateral restraint to errant vehicles, notification exists for crash barriers. Abutments ok, water ingress evident and graffiti removal required. Wingwalls heavily vegetated and obscured. Signage present	
 Do you wish to add another additional comment?	NO	

# OVERALL DCD SCORE

	Script Question	Response	Free Text
	Design score (Current design score: =\$ASSET_1-DS).	4	
	HIDDEN - DESIGN SCORE MEASUREMENT POINT IDENTIFIER.	59813	
	Condition score (Current condition score: =\$ASSET_2-CS).	3	
	HIDDEN - CONDITION SCORE MEASUREMENT POINT IDENTIFIER.	115442	
	Deterioration score (Current deterioration score: =\$ASSET_3-TS).	4	
-	HIDDEN - DETERIORATION SCORE MEASUREMENT POINT IDENTIFIER.	159324	

# PHOTOGRAPHS[1]

Script Question	Response	Free Text
-----------------	----------	-----------

Capture photograph.	Heavy vegetation  Wexford elevation
Photograph description.	N/A
Do you wish to capture another photograph?	YES

# PHOTOGRAPHS[2]

Script Question	Response	Free Text
Capture photograph.	Down Wexford wingwall	
Photograph description.	N/A	
Do you wish to capture another photograph?	YES	

# PHOTOGRAPHS[3]

Script Question	Despense	Free Text
Script Question	Response	Free Text

Capture photograph.	Down abutment
Photograph description.	N/A
Do you wish to capture another photograph?	YES

# PHOTOGRAPHS[4]

Script Question	Response	Free Text
Capture photograph.	Down bearings-corrosion	
Photograph description.	N/A	
Do you wish to capture another photograph?	YES	

# PHOTOGRAPHS[5]

	Capture photograph.	
		Down soffit
	Photograph description.	N/A
-	Do you wish to capture another photograph?	YES

# PHOTOGRAPHS[6]

Script Question	Response	Free Text
Capture photograph.	Down Pearse wingwall	
Photograph description.	N/A	
Do you wish to capture another photograph?	YES	

# PHOTOGRAPHS[7]

Script Question	Response	Free Text

-	Capture photograph.	Pearse elevation
	Photograph description.	N/A
	Do you wish to capture another photograph?	YES

# PHOTOGRAPHS[8]

	Script Question	Response	Free Text
	Capture photograph.	Up pearse wingwall	
	Photograph description.	N/A	
-	Do you wish to capture another photograph?	YES	

# PHOTOGRAPHS[9]

Script Question	Despense	Free Text
Script Question	Response	Free Text

Capture photograph.	Up abutment- water ingress
Photograph description.	N/A
Do you wish to capture another photograph?	YES

# PHOTOGRAPHS[10]

	Script Question	Response	Free Text
	Capture photograph.	Up soffit	
	Photograph description.	N/A	
-	Do you wish to capture another photograph?	YES	

# PHOTOGRAPHS[11]

Capture photograph.	Up bearing corrosion
Photograph description.	N/A
Do you wish to capture another photograph?	YES

# PHOTOGRAPHS[12]

Script Question	Response	Free Text
Capture photograph.	Deck view from up	
Photograph description.	N/A	
Do you wish to capture another photograph?	YES	

# PHOTOGRAPHS[13]

Capture photograph.	Deck view from down	
Photograph description.	N/A	
Do you wish to capture another photograph?	NO	

Condition	Rating
Good (no faults or minor faults well within	1
tolerance)	
Fair (tolerable faults, no restriction in use	2
necessary)	
Poor (significant structural defects, i.e. out-of-	3
tolerance faults)	
Very Poor (seriously deficient, mitigation	4
measures necessary)	

From: To: Cc: Subject: Date: Attachments:	RE: Irish Rail PO - 4501108449 - CANCELLED Tuesday 20 October 2020 08:25:00 image001.jpg image002.png
Hello ,	
	on my e-mail to the Councillors and that we will advise you or our newly scheduled as soon as we have that agreed.
Regards	
From: Sent: 19 Octol To: Cc:	ber 2020 17:23
<b>Subject:</b> RE: Ir	ish Rail PO - 4501108449 - CANCELLED
	This email originated from outside of the organization. Do not click links or open unless you recognize the sender and know the content is safe.
, Thanks so mud	ch for your response , is ok to forward your email below to the Councillors?
Regards,	
Dún Laoghaire-	Roads Control Unit   Municipal Services Department Rathdown County Council   Marine Road   Dún Laoghaire   Co. Dublin
EXT.   D www.dlrcoco.	irect Line Tel + 353 1
	2
Smaoinigh ar an ti	mpeallacht sula ndéanann tú an ríomhphost seo a phriontáil
From: Sent: Wednes To: Cc:	day 14 October 2020 10:55
Subject: RE: Ir	ish Rail PO - 4501108449 - CANCELLED
Hello	

Please be advised that Irish Rail haven't any current structural safety concerns about the use of the railway overbridge at Corbawn Lane. Please be advised that my e-mail address is

as opposed to the e-mail address that you have listed below

### Regards

Infrastructure Manager Dublin Division Irish Rail


From:		
Sent: 09 October 2020 17:27		
То:		
Cc:		
Subject: RE: Irish Rail PO - 4501108449 - CANCELLED		

**CAUTION**: This email originated from outside of the organization. Do not click links or open attachments unless you recognize the sender and know the content is safe.

Dear larnród Éireann,

Please, can I have your comment on my email sent on 30<sup>th</sup> Sept 2020 and highlighted in yellow below.


#### Regards,



Can we have a written letter from Irish Rail confirming that the railway overbridge at Corbawn Lane is currently safe to use until the time it will be renewed. This safety concern was raised during a meeting of Dún Laoghaire Area Committee held on 28th September 2020.

Regards,

Roads Control Unit   Municipal Services Department
Dún Laoghaire-Rathdown County Council   Marine Road   Dún Laoghaire   Co. Dublin  EXT.   Direct Line Tel + 353 1   Email:   DLR Website:
www.dlrcoco.ie
Smaoinigh ar an timpeallacht sula ndéanann tú an ríomhphost seo a phriontáil
From: @irishrail.ie>
Sent: Wednesday 30 September 2020 09:41 To:
Cc:
Subject: RE: Irish Rail PO - 4501108449 - CANCELLED
Thank you.
Regards
RFQ Team Procurement Department Inchicore Works Dublin 8
logo_irishrail
From:
Sent: 30 September 2020 09:36  To:  @irishrail.ie>
Cc: @irishrail.ie>;
Subject: RE: Irish Rail PO - 4501108449 - CANCELLED
CAUTION: This email originated from outside of the organization. Do not click links or open attachments unless you recognize the sender and know the content is safe.
Thanks for your email, I already notified on 18.09.2020 to put the Road Closure application on behalf of Irish Rail on hold until further information.
Regards,
Roads Control Unit   Municipal Services Department Dún Laoghaire-Rathdown County Council   Marine Road   Dún Laoghaire   Co. Dublin



From:

**Sent:** 30 September 2020 09:12

To: @irishrail.ie>
Cc: @irishrail.ie>
Subject: RE: Irish Rail PO - 4501108449 - CANCELLED


CAUTION: This email originated from outside of the organization. Do not click links or open attachments unless you recognize the sender and know the content is safe.

,

Where were the works due to take place?

I don't believe this was something that the parking section was involved in?

Regards,



:: Email Disclaimer Text ::